




MAXXEON™

WorkStar™ I400

The latest product information, FAQs and contact details are available at maxxeon.com.


instructions



To recharge batteries:

1. Turn WorkStar off.
2. Plug charger into outlet, LED: green.
3. Insert charger plug into jack, LED: red.
4. Recharges in under 2 hours, LED: green.

Recharge at any time. Full discharge is not necessary. Cannot be over charged.



Equipped with eight AA NiMH batteries. With normal use, they should last between 2 and 5 years. Replace with identical batteries or upgrade to larger capacity batteries.

High efficiency, constant current regulator provides over 3 hours of full intensity light before switching to a long lasting, low intensity mode.

WARNING: Do not mix old and new batteries or batteries with different capacity ratings. Properly recycle batteries. Do not put batteries in fire or garbage.